



Northern NY Agricultural Development Program 2016-2017: Final Project Report: Photos

Quantifying Long-Term Agronomic and Water Quality Impacts of Tile Drainage in Northern New York



Figure 1, left. Tile drain monitoring setup inside shed for tile-drained field, NNYADP Tile Drainage project, 2017.



Figure 2, center. Flume for measuring surface water runoff for tile-drained field, NNYADP Tile Drainage project, 2017.



Figure 3, right. Flume for measuring surface water runoff for undrained field, NNYADP Tile Drainage project, 2017.



Figure 4, left: Flume capturing surface runoff during snowmelt event on 1/12/18 for undrained field, NNYADP Tile Drainage project, 2017.



Figure 5, right. Flume capturing surface runoff during snowmelt event on 1/12/18 for tile-drained field, NNYADP Tile Drainage project, 2017.